

PROGRAM ADMINISTRATOR DEPARTMENT ALECP INTERTEK 3933 U.S. ROUTE 11 CORTLAND, NY 13045-0950

AIRSAFE AIRPORT EQUIPMENT CO LTD

ROOM 27AB DONGTAI BLDG

NO 309 TANGGU RD

SHANGHAI 200080 PRC

ORIGINAL ISSUE DATE: May 6, 2014

Recertification due: <u>October 2020</u>

An Activity Sponsored and Administered by Intertek

AIRPORT LIGHTING EQUIPMENT CERTIFICATION PROGRAM

CERTIFICATE OF CONFORMANCE

The product described below is hereby approved for listing in the next issue of the Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5345-53, Appendix 3 Addendum "Airport Lighting Equipment Certification Program. The approval is based on successful completion of tests in accordance with the specifications listed in, and the requirements for approval described in the Advisory Circular, and the reporting to the Program Administrator the results of such tests, accompanied by related documents by an Intertek recognized testing laboratory. This Certificate is only confirmable in conjunction with equipment being listed in AC 150/5345-53, Appendix 3, Addendum, as currently published by the FAA. The certification is not valid for a product modified with non-OEM replacement parts or non-production components.

L-861 – Lights, Runway & Taxiway Edge, Medium Intensity (AC 150/5345-46D)		
Manufacturer	Туре	Manufacturer's Catalog Number
		EOL-TE-LED-066-B (593) ief No. 67D additional requirements for "Light d Obstruction Lighting Fixtures" dated March 6,

- 1. This Equipment requires continuing validation in accordance with the requirements of AC 150/5345-53, and the Intertek Airport Lighting Equipment Certification Program.
- 2. Product tested and Report issued by: Intertek

(A) Report No: 100894929CRT-001A; 100894929CRT-003; 100894929CRT-002; 100894929MIN-012; 100894929CRT-005

NOTE: PLEASE REVIEW, AND ADVISE

IF DATA, AS SHOWN, NEED TO BE

ADMINISTRATOR AT INTERTEK IMMEDIATELY

(B) Date of Report: 1/2013; 1/2014; 5/2013; 3/2014; 5/2014

Approved for Certification by:

Jeremy N. Downs, PE, Program Administrator

Date: May 6, 2014

CORRECTED.